Manheim by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	1N4AZ1BV8SC563247	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan LEAF 2025	**Inspector:**	9128
Trim:	S Hatchback	**Inspection Type:**	nmac
Exterior/Interior Color:	QAK - Glacier White / G - Black	**Odometer:**	10589 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	5/32	BRIDGESTONE	205-55-16
RIGHT-REAR	7/32	BRIDGESTONE	205-55-16
SPARE	10/32	OTHER	tire-does-not-exist
LEFT-FRONT	6/32	BRIDGESTONE	205-55-16
LEFT-REAR	6/32	BRIDGESTONE	205-55-16


INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
TOTAL:							**$ 0.00**

Manheim
by Cox Automotive **Vehicle Report Condition**


VIN:	1N4AZ1BV8SC563247	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan LEAF 2025	**Inspector:**	9128
Trim:	S Hatchback		
Exterior/Interior Color:	QAK - Glacier White / G - Black		
Odometer:	10589 Miles		



Front Bumper Chipped 3

Manheim by Cox Automotive **Vehicle Report Condition**

VIN:	1N4AZ1BV8SC563247	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan LEAF 2025	**Inspector:**	9128
Trim:	S Hatchback		
Exterior/Interior Color:	QAK - Glacier White / G - Black		
Odometer:	10589 Miles		



Rear Bumper Gouged 1" to 2"