Manheim by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan	**Inspection Type:**	nmac
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal	**Odometer:**	12837 Miles
Roof Type:	Sun/Moonroof		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	7/32	CONTINENTAL	215-55-17
RIGHT-REAR	6/32	CONTINENTAL	215-55-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	8/32	CONTINENTAL	215-55-17
LEFT-REAR	9/32	CONTINENTAL	215-55-17

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
F Bumper Left Molding	Heavy Mult Scratches	Replacement Required	Replace	0.00	----------	27.89	27.89
Rear Bumper	De-Identify		Flat Fee	0.00	----------	0.00	20.00
TOTAL:							**$ 47.89**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Keyless Remote Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Hood Scratch Heavy 1/2" to 1"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Hood Scratch Heavy 1/2" to 1"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Owners manuals Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**


VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



F Bumper Left Molding Heavy Mult Scratches Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Rear Bumper Chipped 2

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Rear Bumper Chipped 2

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	1N4BL4DV0RN341160	**Inspection Date:**	2026-09-16
Make, Model, & Year:	Nissan Altima 2024	**Inspector:**	10563
Trim:	2.5 SV Sedan		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	12837 Miles		



Rear Bumper De-Identify Removal Required