Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S	**Inspection Type:**	nmac
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal	**Odometer:**	50101 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	9/32	MICHELIN	235-65-17
RIGHT-FRONT	9/32	MICHELIN	235-65-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	7/32	BRIDGESTONE	235-65-17
LEFT-REAR	9/32	MICHELIN	235-65-17


INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Door Molding	Loose	Replacement Required	Replace	9.00	----------	22.94	31.94
LF Seat Cushion	Torn	1/8" to 1/2"	Flat Fee	0.00	----------	0.00	35.00
LR Wheel Opening Mldg	Missing	Replacement Required	Replace	9.00	----------	124.84	133.84
TOTAL:							**$ 200.78**

Manheim by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



LF Seat Cushion Torn 1/8" to 1/2"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



LF Door Molding Loose Repair Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



LF Door Molding Loose Repair Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



LF Tire Mismatched Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



RF Fender Prev Repair Acceptable

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



LF Fender Prev Repair Acceptable

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



LR Wheel Opening Mldg Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



Hood Prev Repair Acceptable

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AA9PC811888	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	50101 Miles		



Front Bumper Prev Repair Acceptable