Manheim by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3AB9PC912812	**Inspection Date:**	2026-09-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6006
Trim:	AWD S	**Inspection Type:**	nmac
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal	**Odometer:**	25995 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	4/32	KUMHO	235-65-17
RIGHT-REAR	4/32	KUMHO	235-65-17
SPARE	5/32	MAXXIS	165-90-17
LEFT-FRONT	4/32	KUMHO	235-65-17
LEFT-REAR	4/32	KUMHO	235-65-17

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
TOTAL:							**$ 0.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB9PC912812	**Inspection Date:**	2026-09-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6006
Trim:	AWD S		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	25995 Miles		



LF Wheel Curb Rash 1/2" to 1"

Manheim
by Cox Automotive **Vehicle Report Condition**


VIN:	5N1BT3AB9PC912812	**Inspection Date:**	2026-09-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6006
Trim:	AWD S		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	25995 Miles		



RF Door Chipped 1

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB9PC912812	**Inspection Date:**	2026-09-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6006
Trim:	AWD S		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	25995 Miles		



LR Door Edge Chipped 1

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB9PC912812	**Inspection Date:**	2026-09-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6006
Trim:	AWD S		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	25995 Miles		



L Qtr Panel Dent/No Paint Dmg 1/8" to 1/2"