Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S	**Inspection Type:**	nmac
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal	**Odometer:**	9704 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	7/32	KUMHO	235-65-17
RIGHT-FRONT	7/32	KUMHO	235-65-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	8/32	KUMHO	235-65-17
LEFT-REAR	8/32	KUMHO	235-65-17

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Front Bumper	Heavy Mult Scratches	10 or More	Body Shop	80.00	152.00	----------	232.00

TOTAL: **$ 232.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S		
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal		
Odometer:	9704 Miles		



Front Bumper Heavy Mult Scratches 10 or More

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S		
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal		
Odometer:	9704 Miles		



RF Door Edge Edge Chipped 3

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S		
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal		
Odometer:	9704 Miles		



Front Bumper Scuffed 4" to 5"

Manheim
by Cox Automotive **Vehicle Report Condition**


VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S		
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal		
Odometer:	9704 Miles		



LF Door Dent/Paint Dmg 2" to 3"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S		
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal		
Odometer:	9704 Miles		



Hood Dent/No Paint Dmg 1" to 2"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3ABXPC885457	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5324
Trim:	AWD S		
Exterior/Interior Color:	NBL - Scarlet Ember Tintcoat / G - Charcoal		
Odometer:	9704 Miles		



R Qtr Panel Light Mult Scratches 3