Manheim by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal	**Odometer:**	23378 Miles
Roof Type:	Panoramic Roof		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	4/32	BRIDGESTONE	235-60-18
RIGHT-FRONT	4/32	BRIDGESTONE	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	4/32	BRIDGESTONE	235-60-18
LEFT-REAR	5/32	BRIDGESTONE	235-60-18

INSPECTION NOTES


CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Roof	Mult Dents/No Paint Dmg		Flat Fee	0.00	----------	0.00	45.00

TOTAL: **$ 45.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Keyless Remote Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



LR Door Scuffed 1/8" to 1/2"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Hood Chipped 6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Hood Chipped 6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Roof Mult Dents/No Paint Dmg PDR/6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Roof Mult Dents/No Paint Dmg PDR/6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Roof Mult Dents/No Paint Dmg PDR/6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Roof Mult Dents/No Paint Dmg PDR/6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



RF Door Light Mult Scratches 2

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA5PW421120	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3178
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	23378 Miles		



Rear Bumper Cover Scuffed 3" to 4"