Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal	**Odometer:**	33681 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	7/32	OTHER	235-60-18
RIGHT-REAR	7/32	OTHER	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	7/32	OTHER	235-60-18
LEFT-REAR	7/32	OTHER	235-60-18

INSPECTION NOTES

tight location, vehicle exterior very dirty

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Front Bumper	Heavy Mult Scratches	4	Body Shop	80.00	152.00	----------	232.00
TOTAL:							**$ 232.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	33681 Miles		



RF Door Mult Dents/No Paint Dmg 3

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	33681 Miles		



RF Door Mult Dents/No Paint Dmg 3

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	33681 Miles		



RF Door Mult Dents/No Paint Dmg 3

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	33681 Miles		



Front Bumper Heavy Mult Scratches 4

Manheim
by Cox Automotive **Vehicle Report Condition**


VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	33681 Miles		



Front Bumper Heavy Mult Scratches 4

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB7PW487161	**Inspection Date:**	2026-09-09
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4796
Trim:	AWD SV		
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal		
Odometer:	33681 Miles		



Front Bumper Heavy Mult Scratches 4