



VIN:	1N4BL4DW8RN326446
Make, Model, & Year:	Nissan Altima 2024
Trim:	2.5 SV AWD Sedan
Exterior/Interior Color:	NBL - Scarlet Ember / Black
Roof Type:	Sun/Moonroof

Inspection Date:	2026-09-14
Inspector:	9820
Inspection Type:	nmac
Odometer:	11850 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	7/32	CONTINENTAL	215-55-17
RIGHT-FRONT	7/32	CONTINENTAL	215-55-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	7/32	CONTINENTAL	215-55-17
LEFT-REAR	6/32	CONTINENTAL	215-55-17

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Front Bumper	Misaligned		Flat Fee	0.00	-----	0.00	80.00
TOTAL:							\$ 80.00



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 1N4BL4DW8RN326446
Make, Model, & Year: Nissan Altima 2024
Trim: 2.5 SV AWD Sedan
Exterior/Interior Color: NBL - Scarlet Ember / Black
Odometer: 11850 Miles

Inspection Date: 2026-09-14
Inspector: 9820



LF Wheel Curb Rash 2" to 3"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 1N4BL4DW8RN326446
Make, Model, & Year: Nissan Altima 2024
Trim: 2.5 SV AWD Sedan
Exterior/Interior Color: NBL - Scarlet Ember / Black
Odometer: 11850 Miles

Inspection Date: 2026-09-14
Inspector: 9820



Front Bumper Misaligned Repair Required