



Inspection Date: 2026-10-08
Inspector: 6352
Inspection Type: nmac
Odometer: 25809 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	5/32	HANKOOK	235-40-19
RIGHT-FRONT	3/32	HANKOOK	235-40-19
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	5/32	HANKOOK	235-40-19
LEFT-REAR	4/32	HANKOOK	235-40-19

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Mirror Housing	Cracked	2" to 3"	Replace	12.00	-----	343.27	355.27
RF Tire	Worn	Replacement Required	Replace	0.00	-----	175.00	175.00
TOTAL:							\$ 530.27



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 1N4BL4EWXPN425751
Make, Model, & Year: Nissan Altima 2023
Trim: 2.5 SL AWD Sedan
Exterior/Interior Color: QAB - Pearl White Tricoat / G - Charcoal
Odometer: 25809 Miles

Inspection Date: 2026-10-08
Inspector: 6352



Rear Glass De-Identify Removal Required



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 1N4BL4EWXPN425751
Make, Model, & Year: Nissan Altima 2023
Trim: 2.5 SL AWD Sedan
Exterior/Interior Color: QAB - Pearl White Tricoat / G - Charcoal
Odometer: 25809 Miles

Inspection Date: 2026-10-08
Inspector: 6352



LF Mirror Housing Cracked 2" to 3"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 1N4BL4EWXPN425751
Make, Model, & Year: Nissan Altima 2023
Trim: 2.5 SL AWD Sedan
Exterior/Interior Color: QAB - Pearl White Tricoat / G - Charcoal
Odometer: 25809 Miles

Inspection Date: 2026-10-08
Inspector: 6352



RF Tire Worn Replacement Required