Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT	**Inspection Type:**	nmac
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal	**Odometer:**	18426 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	3/32	HANKOOK	205-60-16
RIGHT-REAR	7/32	HANKOOK	205-60-16
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	3/32	HANKOOK	205-60-16
LEFT-REAR	7/32	HANKOOK	205-60-16

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Seat	Torn	1" to 2"	Flat Fee	0.00	----------	0.00	35.00
LF Tire	Worn	Replacement Required	Replace	0.00	----------	100.00	100.00
RF Bumper Cover	Cracked	1" to 2"	Replace	0.00	----------	88.87	88.87
RF Tire	Worn	Replacement Required	Replace	0.00	----------	100.00	100.00
RR Tail Lamp	Water Damage	Replacement Required	Replace	9.00	----------	328.42	337.42
TOTAL:							**$ 661.29**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT		
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal		
Odometer:	18426 Miles		



LF Tire Worn Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT		
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal		
Odometer:	18426 Miles		



RR Tail Lamp Water Damage Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT		
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal		
Odometer:	18426 Miles		



RR Tail Lamp Water Damage Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT		
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal		
Odometer:	18426 Miles		



RF Tire Worn Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT		
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal		
Odometer:	18426 Miles		



RF Bumper Cover Cracked 1" to 2"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	3N1AB8CV6PY319894	**Inspection Date:**	2026-08-31
Make, Model, & Year:	Nissan Sentra 2023	**Inspector:**	10108
Trim:	SV CVT		
Exterior/Interior Color:	QAC - Aspen White Tricoat / G - Charcoal		
Odometer:	18426 Miles		



LF Seat Torn 1" to 2"