



VIN:	3N1AB8CVXPY299097	Inspection Date:	2026-09-16
Make, Model, & Year:	Nissan Sentra 2023	Inspector:	7867
Trim:	SV CVT	Inspection Type:	nmac
Exterior/Interior Color:	NBQ - Rosewood Metallic / G - Charcoal	Odometer:	27912 Miles
Roof Type:	Hard Top		

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	1/32	HANKOOK	205-60-16
RIGHT-REAR	4/32	HANKOOK	205-60-16
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	8/32	HANKOOK	205-60-16
LEFT-REAR	4/32	HANKOOK	205-60-16

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
L Qtr Panel	Dent/No Paint Dmg	8" to 9"	Body Shop	200.00	128.00	-----	328.00
RF Tire	Worn	Replacement Required	Replace	0.00	-----	100.00	100.00
TOTAL:							\$ 428.00



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



LF Fender Prev Repair Buffable



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



Hood Prev Repair Buffable



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



Front Bumper Prev Repair Buffable



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



RR Door Dent/No Paint Dmg 1/2" to 1"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



Rear Bumper Dent/No Paint Dmg 1/2" to 1"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



L Qtr Panel Dent/No Paint Dmg 8" to 9"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



RF Fender Dent/No Paint Dmg 1/2" to 1"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 3N1AB8CVXPY299097
Make, Model, & Year: Nissan Sentra 2023
Trim: SV CVT
Exterior/Interior Color: NBQ - Rosewood Metallic / G - Charcoal
Odometer: 27912 Miles

Inspection Date: 2026-09-16
Inspector: 7867



RF Tire Worn Replacement Required