Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3AB5PC876634	**Inspection Date:**	2026-08-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9234
Trim:	AWD S	**Inspection Type:**	nmac
Exterior/Interior Color:	RBY - Caspian Blue Metallic / G - Charcoal	**Odometer:**	33424 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	9/32	GENERIC	235-65-17
RIGHT-FRONT	9/32	GENERIC	235-65-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	9/32	GENERIC	235-65-17
LEFT-REAR	9/32	GENERIC	235-65-17

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Windshield	Star in Glass	1/8" to 1/2"	Flat Fee	0.00	----------	0.00	55.00

TOTAL: **$ 55.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB5PC876634	**Inspection Date:**	2026-08-11
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9234
Trim:	AWD S		
Exterior/Interior Color:	RBY - Caspian Blue Metallic / G - Charcoal		
Odometer:	33424 Miles		



Windshield Star in Glass 1/8" to 1/2"