Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3AB5PC881896	**Inspection Date:**	2026-09-21
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10563
Trim:	AWD S	**Inspection Type:**	nmac
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal	**Odometer:**	26572 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	5/32	OTHER	235-65-17
RIGHT-REAR	6/32	OTHER	235-65-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	5/32	OTHER	235-65-17
LEFT-REAR	6/32	OTHER	235-65-17

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Keyless Remote	Missing		Flat Fee	0.00	----------	0.00	500.00

TOTAL: **$ 500.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB5PC881896	**Inspection Date:**	2026-09-21
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10563
Trim:	AWD S		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	26572 Miles		



Keyless Remote Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB5PC881896	**Inspection Date:**	2026-09-21
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10563
Trim:	AWD S		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	26572 Miles		



Hood Chipped 3

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB5PC881896	**Inspection Date:**	2026-09-21
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10563
Trim:	AWD S		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	26572 Miles		



Front Bumper Light Mult Scratches 3