Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3AB8PC917502	**Inspection Date:**	2026-08-19
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5636
Trim:	AWD S	**Inspection Type:**	nmac
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal	**Odometer:**	30830 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	5/32	KUMHO	235-65-17
RIGHT-FRONT	5/32	KUMHO	235-65-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	5/32	KUMHO	235-65-17
LEFT-REAR	5/32	KUMHO	235-65-17

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
TOTAL:							**$ 0.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB8PC917502	**Inspection Date:**	2026-08-19
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5636
Trim:	AWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	30830 Miles		



R Qtr Panel Dent/Paint Dmg 1/8" to 1/2"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB8PC917502	**Inspection Date:**	2026-08-19
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5636
Trim:	AWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	30830 Miles		



RF Door Edge Chipped 6

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB8PC917502	**Inspection Date:**	2026-08-19
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5636
Trim:	AWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	30830 Miles		



Rear Bumper Light Mult Scratches 10 or More

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3AB8PC917502	**Inspection Date:**	2026-08-19
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	5636
Trim:	AWD S		
Exterior/Interior Color:	QAK - Glacier White / G - Charcoal		
Odometer:	30830 Miles		



Rear Bumper Light Mult Scratches 10 or More