



VIN:	5N1BT3ABXPC931174
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD S
Exterior/Interior Color:	RBV - Caspian Blue Metallic / G - Charcoal
Roof Type:	Hard Top

Inspection Date:	2026-09-16
Inspector:	10334
Inspection Type:	nmac
Odometer:	29371 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	2/32	KUMHO	235-65-17
RIGHT-REAR	2/32	KUMHO	235-65-17
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	2/32	KUMHO	235-65-17
LEFT-REAR	2/32	KUMHO	235-65-17

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Tire	Worn	Replacement Required	Replace	0.00	-----	125.00	125.00
LR Tire	Worn	Replacement Required	Replace	0.00	-----	125.00	125.00
RF Tire	Worn	Replacement Required	Replace	0.00	-----	125.00	125.00
RF Wheel	Curb Rash	9" to 10"	Flat Fee	0.00	-----	0.00	55.00
RR Tire	Worn	Replacement Required	Replace	0.00	-----	125.00	125.00
TOTAL:							\$ 555.00



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



RF Wheel Curb Rash 9" to 10"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



Front Bumper Bug Damage Acceptable



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



RF Tire Worn Replacement Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



LF Tire Worn Replacement Required



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



LF Mirror Cover Scratch Light 2" to 3"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



LF Fender Scratch Light 4" to 5"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



LR Door Light Mult Scratches 4



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



LF Wheel Curb Rash 1" to 2"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3ABXPC931174
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD S
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 29371 Miles

Inspection Date: 2026-09-16
Inspector: 10334



RR Tire Worn Replacement Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3ABXPC931174
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD S
Exterior/Interior Color:	RBV - Caspian Blue Metallic / G - Charcoal
Odometer:	29371 Miles

Inspection Date:	2026-09-16
Inspector:	10334



LR Tire Worn Replacement Required