Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3BA4PC937963	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3553
Trim:	FWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal	**Odometer:**	27234 Miles
Roof Type:	Panoramic Roof		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	8/32	OTHER	235-60-18
RIGHT-REAR	4/32	FALKEN	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	5/32	FALKEN	235-60-18
LEFT-REAR	4/32	FALKEN	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
TOTAL:							**$ 0.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BA4PC937963	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	3553
Trim:	FWD SV		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	27234 Miles		



Front Bumper Bug Damage Acceptable