Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3BA9PC878960	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10443
Trim:	FWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	QAB - Pearl White Tricoat / K - Light Gray	**Odometer:**	25582 Miles
Roof Type:	Sun/Moonroof		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	5/32	FALKEN	235-60-18
RIGHT-REAR	5/32	FALKEN	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	5/32	FALKEN	235-60-18
LEFT-REAR	5/32	FALKEN	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Lift Gate	De-Identify		Flat Fee	0.00	----------	0.00	20.00
TOTAL:							**$ 20.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BA9PC878960	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10443
Trim:	FWD SV		
Exterior/Interior Color:	QAB - Pearl White Tricoat / K - Light Gray		
Odometer:	25582 Miles		



LR Wheel Curb Rash 5" to 6"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BA9PC878960	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10443
Trim:	FWD SV		
Exterior/Interior Color:	QAB - Pearl White Tricoat / K - Light Gray		
Odometer:	25582 Miles		



Lift Gate De-Identify Removal Required