



OVERVIEW

VIN:	5N1BT3BB2PC875861	Inspection Date:	2026-09-16
Make, Model, & Year:	Nissan Rogue 2023	Inspector:	9829
Trim:	AWD SV	Inspection Type:	nmac
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal	Odometer:	26474 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	3/32	HANKOOK	235-60-18
RIGHT-FRONT	3/32	HANKOOK	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	3/32	HANKOOK	235-60-18
LEFT-REAR	4/32	HANKOOK	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
RF Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
RR Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
TOTAL:						\$ 450.00	




Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3BB2PC875861
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: K23 - Brilliant Silver Metallic / G - Charcoal
Odometer: 26474 Miles

Inspection Date: 2026-09-16
Inspector: 9829



RF Tire Worn Replacement Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3BB2PC875861
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: K23 - Brilliant Silver Metallic / G - Charcoal
Odometer: 26474 Miles

Inspection Date: 2026-09-16
Inspector: 9829



RR Tire Worn Replacement Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB2PC875861
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD SV
Exterior/Interior Color:	K23 - Brilliant Silver Metallic / G - Charcoal
Odometer:	26474 Miles

Inspection Date:	2026-09-16
Inspector:	9829



R Qtr Panel Dent/No Paint Dmg 1/8" to 1/2"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB2PC875861
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: K23 - Brilliant Silver Metallic / G - Charcoal
Odometer: 26474 Miles

Inspection Date: 2026-09-16
Inspector: 9829



R Qtr Panel Dent/No Paint Dmg 1/8" to 1/2"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3BB2PC875861
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: K23 - Brilliant Silver Metallic / G - Charcoal
Odometer: 26474 Miles

Inspection Date: 2026-09-16
Inspector: 9829



LF Tire Worn Replacement Required