Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3BB3PC870118	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4932
Trim:	AWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal	**Odometer:**	4231 Miles
Roof Type:	Panoramic Roof		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	9/32	HANKOOK	235-60-18
RIGHT-FRONT	9/32	HANKOOK	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	9/32	HANKOOK	235-60-18
LEFT-REAR	9/32	HANKOOK	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
RF Bumper Cover	Heavy Mult Scratches	4	Body Shop	80.00	152.00	----------	232.00

TOTAL: **$ 232.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB3PC870118	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4932
Trim:	AWD SV		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	4231 Miles		



RF Bumper Cover Heavy Mult Scratches 4

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB3PC870118	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4932
Trim:	AWD SV		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	4231 Miles		



RF Bumper Cover Heavy Mult Scratches 4

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB3PC870118	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4932
Trim:	AWD SV		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	4231 Miles		



Keyless Remote Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB3PC870118	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	4932
Trim:	AWD SV		
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal		
Odometer:	4231 Miles		



Hood Light Mult Scratches 3