Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	5N1BT3BB5PC819221	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6693
Trim:	AWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal	**Odometer:**	11158 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	3/32	HANKOOK	235-60-18
RIGHT-REAR	5/32	GENERAL	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	3/32	HANKOOK	235-60-18
LEFT-REAR	6/32	HANKOOK	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Tire	Worn	Replacement Required	Replace	0.00	----------	150.00	150.00
RF Tire	Worn	Replacement Required	Replace	0.00	----------	150.00	150.00
TOTAL:							**$ 300.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB5PC819221	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6693
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	11158 Miles		



LF Tire Worn Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB5PC819221	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6693
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	11158 Miles		



LF Tire Worn Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB5PC819221	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6693
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	11158 Miles		



RF Tire Worn Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB5PC819221	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6693
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	11158 Miles		



RF Tire Worn Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB5PC819221	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	6693
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	11158 Miles		



Owners manuals Missing Replacement Required