



VIN:	5N1BT3BB6PC859548
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD SV
Exterior/Interior Color:	KAD - Gun Metallic / G - Charcoal
Roof Type:	Panoramic Roof

Inspection Date:	2026-09-16
Inspector:	10043
Inspection Type:	nmac
Odometer:	36729 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	3/32	HANKOOK	235-60-18
RIGHT-REAR	4/32	HANKOOK	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	3/32	HANKOOK	235-60-18
LEFT-REAR	4/32	HANKOOK	235-60-18

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
RF Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
TOTAL:							\$ 300.00



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB6PC859548
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KAD - Gun Metallic / G - Charcoal
Odometer: 36729 Miles

Inspection Date: 2026-09-16
Inspector: 10043



Owners manuals Missing Replacement Required



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB6PC859548
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KAD - Gun Metallic / G - Charcoal
Odometer: 36729 Miles

Inspection Date: 2026-09-16
Inspector: 10043



RF Tire Worn Replacement Required



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB6PC859548
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KAD - Gun Metallic / G - Charcoal
Odometer: 36729 Miles

Inspection Date: 2026-09-16
Inspector: 10043



Warning - Tire Pressure On Unacceptable



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3BB6PC859548
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KAD - Gun Metallic / G - Charcoal
Odometer: 36729 Miles

Inspection Date: 2026-09-16
Inspector: 10043



LF Tire Worn Replacement Required