



OVERVIEW

VIN:	5N1BT3BB6PC886961	Inspection Date:	2026-10-06
Make, Model, & Year:	Nissan Rogue 2023	Inspector:	10046
Trim:	AWD SV	Inspection Type:	nmac
Exterior/Interior Color:	RBV - Caspian Blue Metallic / G - Charcoal	Odometer:	21172 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	3/32	HANKOOK	235-60-18
RIGHT-REAR	4/32	HANKOOK	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	3/32	HANKOOK	235-60-18
LEFT-REAR	5/32	HANKOOK	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
LF Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
RF Tire	Worn	Replacement Required	Replace	0.00	-----	150.00	150.00
RF Wheel	Curb Rash	7" to 8"	Flat Fee	0.00	-----	0.00	55.00

TOTAL:

\$ 355.00



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3BB6PC886961
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 21172 Miles

Inspection Date: 2026-10-06
Inspector: 10046



RF Fender Prev Repair Acceptable




Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB6PC886961
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 21172 Miles

Inspection Date: 2026-10-06
Inspector: 10046



RF Wheel Curb Rash 7" to 8"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB6PC886961
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 21172 Miles

Inspection Date: 2026-10-06
Inspector: 10046



RF Wheel Curb Rash 7" to 8"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: 5N1BT3BB6PC886961
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 21172 Miles

Inspection Date: 2026-10-06
Inspector: 10046



Windshield Chipped < 1/8"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB6PC886961
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD SV
Exterior/Interior Color:	RBV - Caspian Blue Metallic / G - Charcoal
Odometer:	21172 Miles

Inspection Date:	2026-10-06
Inspector:	10046



LF Tire Worn Replacement Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN:	5N1BT3BB6PC886961
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD SV
Exterior/Interior Color:	RBV - Caspian Blue Metallic / G - Charcoal
Odometer:	21172 Miles

Inspection Date:	2026-10-06
Inspector:	10046



Front Bumper Prev Repair Acceptable



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: 5N1BT3BB6PC886961
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: RBY - Caspian Blue Metallic / G - Charcoal
Odometer: 21172 Miles

Inspection Date: 2026-10-06
Inspector: 10046



RF Tire Worn Replacement Required