



Inspection Date:	2026-09-24
Inspector:	5049
Inspection Type:	nmac
Odometer:	19078 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	4/32	OTHER	225-50-18
RIGHT-FRONT	4/32	OTHER	225-50-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	4/32	OTHER	225-50-18
LEFT-REAR	4/32	OTHER	225-50-18

--

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
TOTAL:							\$ 0.00




Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN1EV7BRXPM540957
Make, Model, & Year: INFINITI Q50 2023
Trim: LUXE AWD
Exterior/Interior Color: KH3 - Black Obsidian / G - Graphite
Odometer: 19078 Miles

Inspection Date: 2026-09-24
Inspector: 5049



Deck Lid Dent/No Paint Dmg 1/8" to 1/2"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN1EV7BRXPM540957
Make, Model, & Year: INFINITI Q50 2023
Trim: LUXE AWD
Exterior/Interior Color: KH3 - Black Obsidian / G - Graphite
Odometer: 19078 Miles

Inspection Date: 2026-09-24
Inspector: 5049



Owners manuals Missing Replacement Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN1EV7BRXPM540957
Make, Model, & Year: INFINITI Q50 2023
Trim: LUXE AWD
Exterior/Interior Color: KH3 - Black Obsidian / G - Graphite
Odometer: 19078 Miles

Inspection Date: 2026-09-24
Inspector: 5049



Front Bumper Cover Chipped 8



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN1EV7BRXPM540957
Make, Model, & Year: INFINITI Q50 2023
Trim: LUXE AWD
Exterior/Interior Color: KH3 - Black Obsidian / G - Graphite
Odometer: 19078 Miles

Inspection Date: 2026-09-24
Inspector: 5049



Hood Dent/No Paint Dmg 1/8" to 1/2"