



OVERVIEW

VIN:	JN8BT3BA7PW429297	Inspection Date:	2026-10-06
Make, Model, & Year:	Nissan Rogue 2023	Inspector:	10148
Trim:	FWD SV	Inspection Type:	nmac
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal	Odometer:	6048 Miles
Roof Type:	Sun/Moonroof		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	8/32	BRIDGESTONE	235-60-18
RIGHT-FRONT	6/32	BRIDGESTONE	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	7/32	BRIDGESTONE	235-60-18
LEFT-REAR	8/32	BRIDGESTONE	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Front Bumper Cover	Heavy Mult Scratches	5	Body Shop	80.00	152.00	-----	232.00
RF Door	Dent/Paint Dmg	6" to 7"	Body Shop	160.00	128.00	-----	288.00
RF Wheel Cover	Curb Rash	GR 12"	Flat Fee	0.00	-----	0.00	25.00

TOTAL:

\$ 545.00



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Door Dent/Paint Dmg 6" to 7"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Fender Dent/Paint Dmg 1" to 2"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Wheel Cover Curb Rash GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Wheel Cover Curb Rash GR 12"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Wheel Cover Curb Rash GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Wheel Cover Curb Rash GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



RF Wheel Cover Curb Rash GR 12"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



Front Bumper Cover Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



Front Bumper Cover Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



Front Bumper Cover Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



Front Bumper Cover Heavy Mult Scratches 5



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BA7PW429297
Make, Model, & Year: Nissan Rogue 2023
Trim: FWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 6048 Miles

Inspection Date: 2026-10-06
Inspector: 10148



Front Bumper Cover Heavy Mult Scratches 5