Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	JN8BT3BA8PW425100	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal	**Odometer:**	18423 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	4/32	DUNLOP	235-60-18
RIGHT-REAR	8/32	GOODYEAR	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	4/32	DUNLOP	235-60-18
LEFT-REAR	5/32	DUNLOP	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
TOTAL:							**$ 0.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA8PW425100	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	18423 Miles		



RF Wheel Curb Rash 3" to 4"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA8PW425100	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	18423 Miles		



RR Tire Mismatched Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA8PW425100	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	18423 Miles		



Front Bumper Scraped 2" to 3"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BA8PW425100	**Inspection Date:**	2026-09-14
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	10081
Trim:	FWD SV		
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal		
Odometer:	18423 Miles		



Front Bumper Scuffed 3" to 4"