Manheim
by Cox Automotive **Vehicle Report Condition**

OVERVIEW

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV	**Inspection Type:**	nmac
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray	**Odometer:**	42500 Miles
Roof Type:	Hard Top		

TIRES

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	8/32	FIRESTONE	235-60-18
RIGHT-FRONT	8/32	FIRESTONE	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	8/32	FIRESTONE	235-60-18
LEFT-REAR	7/32	FIRESTONE	235-60-18

INSPECTION NOTES

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Front Bumper	Scraped	3" to 4"	Body Shop	40.00	152.00	----------	192.00

TOTAL: **$ 192.00**

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



R Qtr Panel Scratch Light 7" to 8"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



Front Bumper Scraped 3" to 4"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



Front Bumper Scraped 3" to 4"

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



LF Seat Stained Permanent

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



Owners manuals Missing Replacement Required

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



LR Door Light Mult Scratches 10 or More

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



LR Door Light Mult Scratches 10 or More

Manheim
by Cox Automotive **Vehicle Report Condition**

VIN:	JN8BT3BB8PW490831	**Inspection Date:**	2026-09-15
Make, Model, & Year:	Nissan Rogue 2023	**Inspector:**	9820
Trim:	AWD SV		
Exterior/Interior Color:	KH3 - Super Black / K - Light Gray		
Odometer:	42500 Miles		



LR Door Light Mult Scratches 10 or More