



VIN:	JN8BT3BB9PW498694
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD SV
Exterior/Interior Color:	White / K - Light Gray
Roof Type:	Panoramic Roof

Inspection Date:	2026-09-19
Inspector:	6433
Inspection Type:	nmac
Odometer:	37308 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-REAR	6/32	OTHER	235-60-18
RIGHT-FRONT	6/32	OTHER	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	6/32	OTHER	235-60-18
LEFT-REAR	6/32	OTHER	235-60-18

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Lift Gate	De-Identify		Flat Fee	0.00	-----	0.00	20.00
R Qtr Panel	Scratch Heavy	GR 12"	Body Shop	80.00	128.00	-----	208.00
Rear Bumper Molding	Cracked	1" to 2"	Body Shop	0.00	56.00	-----	56.00
RR Door	Dent/Paint Dmg	5" to 6"	Body Shop	140.00	128.00	-----	268.00

TOTAL:	\$ 552.00
---------------	------------------



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Rear Bumper Molding Cracked 1" to 2"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Rear Bumper Molding Cracked 1" to 2"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Front Bumper Scratch Heavy 1/8" to 1/2"




Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Front Bumper Scratch Heavy 1/8" to 1/2"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Keys Missing Replacement Required



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



RR Door Dent/Paint Dmg 5" to 6"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



RR Door Dent/Paint Dmg 5" to 6"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



R Qtr Panel Scratch Heavy GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



R Qtr Panel Scratch Heavy GR 12"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Lift Gate De-Identify Removal Required



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BB9PW498694
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: White / K - Light Gray
Odometer: 37308 Miles

Inspection Date: 2026-09-19
Inspector: 6433



Lift Gate De-Identify Removal Required