



VIN:	JN8BT3BBXPW486974
Make, Model, & Year:	Nissan Rogue 2023
Trim:	AWD SV
Exterior/Interior Color:	KH3 - Super Black / G - Charcoal
Roof Type:	Hard Top

Inspection Date:	2026-09-12
Inspector:	9779
Inspection Type:	nmac
Odometer:	44120 Miles

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	7/32	OTHER	235-60-18
RIGHT-REAR	7/32	OTHER	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	7/32	OTHER	235-60-18
LEFT-REAR	6/32	KUMHO	235-60-18

CHARGEABLE WEAR AND USE

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
Front Bumper	Heavy Mult Scratches	5	Body Shop	80.00	152.00	-----	232.00
LF Fender	Dent/No Paint Dmg	GR 12"	Body Shop	260.00	112.00	-----	372.00
TOTAL:							\$ 604.00



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



RF Door Dent/No Paint Dmg 1/2" to 1"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



LF Fender Dent/No Paint Dmg GR 12"



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



LF Fender Dent/No Paint Dmg GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



LF Fender Dent/No Paint Dmg GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



LF Fender Dent/No Paint Dmg GR 12"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



Front Bumper Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



Front Bumper Heavy Mult Scratches 5



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



Front Bumper Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



Front Bumper Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



Front Bumper Heavy Mult Scratches 5



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BBXPW486974
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: KH3 - Super Black / G - Charcoal
Odometer: 44120 Miles

Inspection Date: 2026-09-12
Inspector: 9779



L Qtr Panel Dent/No Paint Dmg PDR/1