



VIN:	JN8BT3BBXPW490264	Inspection Date:	2026-09-28
Make, Model, & Year:	Nissan Rogue 2023	Inspector:	3188
Trim:	AWD SV	Inspection Type:	nmac
Exterior/Interior Color:	Gray / Black	Odometer:	13655 Miles
Roof Type:	Hard Top		

Part	Tread Depth	Manufacturer	Size
RIGHT-FRONT	5/32	BRIDGESTONE	235-60-18
RIGHT-REAR	7/32	BRIDGESTONE	235-60-18
SPARE	10/32	OTHER	compact-spare
LEFT-FRONT	5/32	BRIDGESTONE	235-60-18
LEFT-REAR	7/32	BRIDGESTONE	235-60-18

Part Description	Damage Type	Severity	Labor Operation	Labor Total	Paint Total	Part Cost	Total
RR Door	Heavy Mult Scratches	5	Body Shop	80.00	128.00	-----	208.00
TOTAL:							\$ 208.00



Manheim

by Cox Automotive **Vehicle Report Condition**

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



Front Bumper Heavy Mult Scratches 2



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



R Bumper Textured Heavy Mult Scratches 2



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



R Bumper Textured Heavy Mult Scratches 2



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



LR Door Dent/Paint Dmg 2" to 3"




Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



Front Bumper Light Mult Scratches 4



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



RR Door Heavy Mult Scratches 5



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



LR Door Scratch Heavy 1" to 2"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



R Qtr Panel Molding Light Mult Scratches 4



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



L Qtr Panel Dent/No Paint Dmg 1" to 2"



Manheim

by Cox Automotive

Vehicle Report Condition

VIN: JN8BT3BBXPW490264
Make, Model, & Year: Nissan Rogue 2023
Trim: AWD SV
Exterior/Interior Color: Gray / Black
Odometer: 13655 Miles

Inspection Date: 2026-09-28
Inspector: 3188



Owners manuals Missing Replacement Required